

Oil Field Environmental Incident Summary

Incident: 20151019093725 **Date/Time of Notice:** 10/19/2015 09:37
Responsible Party: MUREX PETROLEUM CORPORATION
Well Operator: MUREX PETROLEUM CORPORATION
Well Name: HALEY MARIE 1-12H
Field Name: WRITING ROCK **Well File #:** 25875
Date Incident: 10/17/2015 **Time Incident:** 05:00 **Facility ID Number:**
County: DIVIDE **Twp:** 161 **Rng:** 101 **Sec:** 1 **Qtr:**
Location Description: Lot #3

Submitted By: William Jansky **Received By:**

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pump Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	90	Barrels	89	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

The power fluid tank was shut in, and vacuum truck called for fluid recovery.

Wastes Disposal Location: Production tanks

Agencies Involved:

Updates

Date: 10/19/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a pump leak, remained on location according to the report. NDIC retains oversight.